

Flexible Vehicle-Mounted Magnets

Instructions for use and care:

Storing the Magnet

When not using the magnet, keep it in a clean and dry place.
Store the magnet on a horizontal, smooth and flat surface. Avoid placing objects on top of it.

Preparing Magnetic Receptive Surface

Make sure that the surface paints, clear coats and waxes on the metal surface are properly cured (normal curing time: car paint – 90 days, clear coat - 60 days, wax - 2days).
After waxing and polishing, allow 2 days to cure before applying magnets.
Clean the metal surface and the magnet with mild detergent. Allow them to air-dry or wipe with a soft cloth.

Applying the Magnet

Make sure both the magnet and the metal surface are dry before applying the magnet.
Affix the magnet to smooth, flat or gently curved metal surfaces.
Make sure that the entire magnet is flat against the metal surface (i.e. no air pockets).
Always remove magnet by pulling it off the metal surface. Never remove it by pulling it across the surface.
Avoid use on metal surfaces exposed to direct sunlight.
End-use temperature range: -15° F to 130° F (-26° C to 55° C). Short term resistance: 150° F (66° C). Avoid use at temperatures outside end-use temperature range.
Long-term use on surfaces frequently exposed to sunlight can result in uneven fading of the surface.
Avoid use on non-metallic body fillers, simulated wood grain siding and repainted surfaces.

Cleaning the Magnet

Remove the magnet and clean both the magnet and the metal surface with mild detergent DAILY.
Allow them to air-dry or wipe with a soft cloth.

Keeping the Magnet Clean and Dry

Remove the magnet during car wash. Make sure the magnet and the metal surface are clean and dry before reapplying.

Avoid water such as rainwater, car wash water and dew water being trapped between the magnet and the metal surface. In case water is trapped, remove the magnet as soon as possible, clean and dry the magnet and the metal surface, place the magnet with magnetized side facing upwards at a ventilated and dried surface for at least 2 hours. Reapply the magnet when it is dried.

Caution

Applying the magnet to a painted vehicle surface without following the above instructions may result in damage to the magnet and the metal surface. The supplier will not be held liable for any damage caused by abuse, misuse or failure to follow these instructions.